PORTLAND HARBOR RI/FS REMEDIAL INVESTIGATION REPORT

APPENDIX D4.3 CONTAMINANTS IN TRANSITION ZONE WATER AND SEEPS—FIGURES

DRAFT FINAL

LIST OF FIGURES

Figure D4.3-1.	Scatter Plots of Cadmium Concentrations in Transition Zone Water, Filtered and Unfiltered Peeper Samples
Figure D4.3-2.	Scatter Plots of Lead Concentrations in Transition Zone Water, Filtered and Unfiltered Peeper Samples
Figure D4.3-3.	Scatter Plots of Nickel Concentrations in Transition Zone Water, Filtered and Unfiltered Peeper Samples
Figure D4.3-4.	Scatter Plots of Manganese Concentrations in Transition Zone Water, Filtered and Unfiltered Peeper Samples




Figure D4.3-1
Portland Harbor RI/FS
Remedial Investigation Report
Scatter Plots of Cadmium Concentrations in Transition Zone Water,
Filtered and Unfiltered Peeper Samples





Figure D4.3-2
Portland Harbor RI/FS
Remedial Investigation Report
Scatter Plots of Lead Concentrations in Transition Zone Water,
Filtered and Unfiltered Peeper Samples







Figure D4-3-3
Portland Harbor RI/FS
Remedial Investigation Report
Scatter Plots of Nickel Concentrations in Transition Zone Water,
Filtered and Unfiltered Peeper Samples








Figure D4.3-4
Portland Harbor RI/FS
Remedial Investigation Report
Scatter Plots of Manganese Concentrations in Transition Zone Water,
Filtered and Unfiltered Peeper Samples